
















# PT Soldering tips

## Chisel shape



A = Width mm  
 B = Thickness mm  
 C = Length mm

Model	A	B	C	Temperature °C	PU	Order No.
<b>PTA6</b> 	1.6	0.7	33	310	1	PTA6
<b>PTA7</b> 	1.6	0.7	33	370	1	PTA7
<b>PTA8</b> 	1.6	0.7	33	425	1	PTA8
<b>PTB6</b> 	2.4	0.8	33	310	1	PTB6
<b>PTB8</b> 	2.4	0.8	33	425	1	PTB8
<b>PTC7</b> 	3.2	0.8	33	370	1	PTC7
<b>PTC8</b> 	3.2	0.8	33	425	1	PTC8
<b>PTD7</b> 	4.6	0.8	33	370	1	PTD7
<b>PTD8</b> 	4.6	0.8	33	425	1	PTD8
<b>PTE8</b> 	5.6	1.2	33	425	1	PTE8
<b>PTH6</b> 	0.8	0.4	35	310	1	PTH6
<b>PTH7</b> 	0.8	0.4	35	370	1	PTH7
<b>PTH8</b> 	0.8	0.4	35	425	1	PTH8











Model	A	B	C	Temperature °C	PU	Order No.
<b>PTK6</b> 	1.2	0.4	42	310	1	PTK6
<b>PTK7</b> 	1.2	0.4	42	370	1	PTK7
<b>PTK8</b> 	1.2	0.4	42	425	1	PTK8
<b>PTL7</b> 	2.0	1.0	42	370	1	PTL7
<b>PTL8</b>	2.0	1.0	42	425	1	PTL8
<b>PTM7</b> 	3.2	1.2		370	1	PTM7
<b>PTM8</b> 	3.2	1.2		425	1	PTM8
<b>PTR7</b> 	1.6	0.7	33	370	1	PTR7
<b>PTR8</b> 	1.6	0.7	33	425	1	PTR8

**Round**






A = Width mm  
B = Thickness mm  
C = Length mm

Model	A	B	C	Temperature °C	PU	Order No.
<b>PTAA7</b> 	1.6		33	370	1	PTAA7
<b>PTAA8</b> 	1.6		33	425	1	PTAA8
<b>PTBB7</b> 	2.4		34.5	370	1	PTBB7
<b>PTBB8</b> 	2.4		34.5	425	1	PTBB8
<b>PTCC7</b> 	3.2		33	370	1	PTCC7
<b>PTCC8</b> 	3.2		33	425	1	PTCC8
<b>PTF7</b> 	1.2		33	370	1	PTF7
<b>PTO7</b> 	0.8		44	370	1	PTO7



## Soldering tips and nozzles | Soldering tips

Model	A	B	C	Temperature °C	PU	Order No.
<b>PT08</b> 	0.8		44	425	1	PT08
<b>PTS7</b> 	0.4		44	370	1	PTS7
<b>PTS8</b> 	0.4		44	425	1	PTS8