








# WTA Soldering tips

## Chisel shape



A = Width mm  
B = Thickness mm  
C = Length mm

Model	A	B	C	PU	Order No.
<b>WTA 1</b> 	1.0	0.5		1	T005 44 141 99
<b>WTA 2</b> 	3.0	0.5		1	T005 44 146 99
<b>WTA 3</b> 	6.0	0.5		1	T005 44 147 99

Model	A	B	C	PU	Order No.
<b>WTA 4</b> 	12.5	0.5		1	T005 44 143 99
<b>WTA 5</b> 	18.5	0.5		1	T005 44 144 99